Nº 11435

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	
	No Inspection
	· ,
	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 11435

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICI

PERMIT TO TAP SEWER

A , MASSILLON, OHIO, $A$
RECEIVED OF / Suchery Uniching FEE OF \$
FOR WHICH PERMISSION IS GRANTED
REPAIR TO TAP
OF
THE PREMISES BEING LOT NO. 3420 HOUSE NO. 1/17
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR
A second

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.