

Nº 11439

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 3/12/02

HOUSE NO. 2395

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM


Tapped into MH

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

NAME OF CONTRACTOR

Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11439

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 03/04/03

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Malavite Excavating

REPAIR TO TAP CUTOFF tap sanitary SEWER ON THE south S

OF Wilmington Ave SE AVE. ST. TYPE OF STREET curb cut

THE PREMISES BEING LOT NO. 16287, HOUSE NO. 2395

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.