


Nº 11441

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/12/02 IF SO, HOW AND LOCATION FROM 140'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 2465
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malivite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11441

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

3/6/20

RECEIVED OF _____

Malawite

FEE OF \$ _____

57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

North

S

OF _____

Wilbur

AVE.

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO. _____

16254

HOUSE NO. _____

2465

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Debraquished Horner

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.