


N^o 11446

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/12/02 IF SO, HOW AND LOCATION FROM 176'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1080
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR John's Excavating
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Yappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11446

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/11/20
RECEIVED OF Johns Excavating ck# 5398 FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sp. Sanitary SEWER ON THE East S
CUTOFF _____

OF Franklin St. AVE. TYPE OF STREET Arterial

THE PREMISES BEING LOT NO. 16015, HOUSE NO. 51080

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Klatt Homes

398

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.