## $N^{\circ}$ 11450

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4/11/02  HOUSE NO. 2245  SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? yes	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Romans Plumbing
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.  2245 Ria Grends  22291'  45' -28'  73'
SIGNED BIT Pappas Inspector for City	FILED AT ENGINEER'S OFFICE

## Nº 11450

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		// A	I, OHIO,	3,	/, 204
RECEIVED OF	- And	in Flun	illedg :	FEE OF \$	<u>ڻ</u>
FOR WHICH PERMISSION IS GRAI	NTED				
REPAIR TO TAP	Ash. M.	SEWER ON THE		ALLAK	
CUTOFFT AUGUS	udi Ca	AVE. STATTPE OF STREET		with the	
THE PREMISES BEING LOT NO	/	5907	, HOUSE NO	23.45	
	ŕ	/			
WORK TO BE DONE IN ACCORDA	NCE WITH ORDINAN	ICE NO. 19.1971 DULY PA	SSED BY THE CITY CO	DUNCIL, AND RULES O	FTHE
DEPARTMENT OF PUBLIC SERVIC	E. ()(	P and			
NAME OF CONTRACTOR	1 7 C	Migt			
	*	U			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.