


N^o 11454

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/2/02 IF SO, HOW AND LOCATION FROM 33'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 30
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Buckeye
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Jeffrey M. King Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11454

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/15 20

RECEIVED OF Buckeye

FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE East

S

OF 116th St

AVE.

ST. TYPE OF STREET duplex

THE PREMISES BEING LOT NO. 16372

HOUSE NO. 30

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Buckeye

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

duplex