Νº	1	1	4	5	7

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	CONDITINE AND DEL TIT
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.
	No Inspection
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	·
REMARKS	

Nº 11457

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

/	MASSILLON, C	OHIO,	3/120
RECEIVED OF	<i>y</i>		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	<i>J</i>	***************************************	
REPAIR TO TAP	SEWER ON THE	10 mg 1 mg	4 7 A
OF CUTOFF S	VE T. TYPE OF STREET	A distant	
THE PREMISES BEING LOT NO.	1 / *3 .55 m.	HOUSE NO.	1108
			•
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	IO. 19.1971 DULY PASS	ED BY THE CITY COUNC	IL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	Alex Com		
	Λ		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

Cur