FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/19/02	_ IF SO, HOW AND LOCATION FROM 154		
HOUSE NO.	2811	FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN	yes	Triple Diamond NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
SIGNED FILED AT ENGINEER'S OFFICE				
	Inspector for City			

Nº 11460

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF July	MASSILLON, OHIO,	3//9,20_
7	1	
FOR WHICH PERMISSION IS GRANTED		
TO TAP	SEWER ON THE	well still s
CUTOFF	/E	•
<i>A</i> ! '	2/02, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	O. 19.1971 DULY PASSED BY THE	ECITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	e Allandonia	Le in file to make

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.