


Nº 11461

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/20/02 IF SO, HOW AND LOCATION FROM 205'  
FIRST MANHOLE DOWN STREAM  
HOUSE NO. 2445  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? yes  
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malavite  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED *Jeffrey M. [Signature]* Inspector for City FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

N<sup>o</sup> 11461

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/19 2019

RECEIVED OF Malawite

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR  
TO TAP  
CUTOFF

SEWER ON THE

OF

AVE.  
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Reitzger & Sons

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**