Nº 11463

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/27/02	IF SO, HOW AND LOCATION FROM	123'		
HOUSE NO.	1025	FIRST MANHOLE DOWN STREAM	120	<del></del>	
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Kevin Glick	<del></del>	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
		÷	-15'-1 1025 Landole		
			-39'	_	
			9'dp -	$\longrightarrow$	
		·	123'		
SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE					
REMARKS					

## $N^{\circ}$ 11463

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIO, —	FEE OF, \$
FOR WHICH PERMISSION IS GRANTED	wallenger was the state of the	ener to
REPAIR O TAP CUTOFF	SEWER ON THE	<u>durat</u> e
OF	ST. TYPE OF STREET	and the state of t
THE PREMISES BEING LOT NO		NO
DEPARTMENT OF PUBLIC SERVICE.	ORDINANCE NO. 18.1971 DULY PASSED BY TH	HE CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	At XINGOLD	<del></del>

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.