Nº 11465

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/26/02	IF SO, HOW AND LOCATION FROM	80'			
HOUSE NO.	2485	FIRST MANHOLE DOWN STREAM				
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT				
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH				
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Malavite			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.						
		N -	2485 Wilmington 55 10'- 10'			
	•	80'	+			
SIGNED W	Inspector for City	FILED AT ENGINEER'S (DFFICE			
REMARKS			•			

Nº 11465

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	****	MASSILLO	N, OHIO,	оню,		
RECEIVED OF	11/10/2	to the facility		FEE OF \$	^بر <u>المح</u>	
FOR WHICH PERMISSION IS GF	IANTED		· · · · · · · · · · · · · · · · · · ·	T STATE OF THE STA		
TO TAP CUTOFF U. D. COLOR	Later Eller	SEWER ON THEAVE	- <u>/// / / / / / / / / / / / / / / / / /</u>	<u> 18. januari - </u>	<u> </u>	
THE PREMISES BEING LOT NO.	J //6	213	, HOUSE NO	12005		
WORK TO BE DONE IN ACCORD DEPARTMENT OF PUBLIC SERV		CE NO. 19.1971 DULY PA	ASSED BY THE CITY C	OUNCIL, AND RULES OF T	ΉE	
NAME OF CONTRACTOR	<u> </u>	<u>Ict</u>	***************************************			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.