

Nº 11468


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/1/02 IF SO, HOW AND LOCATION FROM 156'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1825
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR John's Excavating
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



156'



SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11468

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April, 2019

RECEIVED OF JOHN'S EXCAVATING FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED HANNAH FLOOR JOHN'S EX

REPAIR
TO TAP SEWER ON THE GREENFIELD LKS
CUTOFF

OF GREENFIELD AVE. 1415 ASPHALT
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 15732, HOUSE NO. 1875

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR JOHN'S EXCAVATING

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**