

Nº 11469

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/1/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

24'

HOUSE NO. 1835

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR John's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11469

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, APRIL, 201

RECEIVED OF JOHN'S EXCAVATING FEE OF \$ 100.00

FOR WHICH PERMISSION IS GRANTED JOHN'S EXCAVATING

REPAIR
TO TAP SANITARY SEWER ON THE WEST S
CUTOFF

OF GREENTREE PLACE AVE.
ST. TYPE OF STREET ACADEMY

THE PREMISES BEING LOT NO. 15733, HOUSE NO. 1835

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR JOHN'S EXCAVATING

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**