

N^o 11475

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 3/28/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 299'

HOUSE NO. 2133

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR H&W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11475

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

4/1/20

RECEIVED OF _____

7/1/20

FEE OF \$ _____

52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

West

S

OF _____

University Community SE

AVE.
ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO. _____

06899

, HOUSE NO. _____

2133

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Loain

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**