


Nº 11479

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/16/02 IF SO, HOW AND LOCATION FROM 160'  
FIRST MANHOLE DOWN STREAM  
HOUSE NO. 1375  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? yes  
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*N* →



Not to scale

SIGNED *[Signature]* FILED AT ENGINEER'S OFFICE \_\_\_\_\_  
Inspector for City

REMARKS \_\_\_\_\_

N<sup>o</sup> 11479

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/9 1920

RECEIVED OF

Malanite

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

REPAIR  
TO TAP  
CUTOFF

Sanitary  
Amade St

SEWER ON THE

West

S

OF

AVE

AT TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

16054

HOUSE NO.

4375

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malanite

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**