


Nº 11480

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/16/02 IF SO, HOW AND LOCATION FROM 170'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 270
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malevite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11480

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 09/10/02, 20

RECEIVED OF FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Malavite Excavating

REPAIR TO TAP tap sanitary SEWER ON THE East S
CUTOFF

OF Stockport Ave. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15177, HOUSE NO. 270

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.