

Nº 11484

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/16/02

HOUSE NO. 724

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 217'

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

NAME OF CONTRACTOR K Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11484

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

4/15/20

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP ____
CUTOFF

SEWER ON THE

OF

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.