Nº 11486

REMARKS _

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	4/23/02	IF SO, HOW AND LOCATION FROM	T 1
HOUSE NO.	1925	FIRST MANHOLE DOWN STREAM	Tapped into MH
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	yes		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR Gase Western DR-SE	Malavite
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF BU	JILDING SERVED.	
		15'	Z >
Not to scale			
	.1.		
SIGNED Bill Pap	OR 5 Inspector for City	FILED AT ENGINEER'S OFFICE	·

Nº 11486

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

į.	MASSILLON	N, OHIO,	4/.209
RECEIVED OF	Malauite	FEE OF \$	57
OR WHICH PERMISSION IS GRAN	TED		
REPAIR TO TAP CUTOFF	SEWER ON THE	Labet	SI
DF	AVE. ST. TYPE OF STREET	Madhas	<u> </u>
THE PREMISES BEING LOT NO	15966	_, HOUSE NO	Past
	CE WITH ORDINANCE NO. 19.1971 DULY PA	SSED BY THE CITY COUNCIL, AND F	RULES OF THE
DEPARTMENT OF PUBLIC SERVICE	- / _/		2
NAME OF CONTRACTOR	South Home	All Allen	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.