

Nº 11487

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

4/26/02

280'

DATE INSPECTED _____ 2425 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____ 6"


SIZE OF PIPE USED _____ yes DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT

WAS LATERAL AT CURB? _____ yes CURB LINE AND DEPTH _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11487

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/19, 200

RECEIVED OF Malcolm

FEE OF \$ 52

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE

OF

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**