## Nº 11491

REMARKS \_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	5/14/02	IF SO, HOW AND LOCATION FROM	2.1			
HOUSE NO	440	THE WAY OLD BOTT BITTER				
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT				
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH				
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	H&W			
SHOW BY DIAGRAM RELATIO	N OF LATERAL TO WALL OF B	UILDING SERVED.	24- 24- 24- 18'	N		
Not to scale		-	·	a		
SIGNED WILL IN LA	Inspector for City	FILED AT ENGIN	NEER'S OFFICE			

## Nº 11491

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		MASSILLON	, OHIO,	04/30/00	<u>ኢ</u>
RECEIVED OF	H. W	Contractor	<u>s //-</u>	FEE OF \$	
FOR WHICH PERMISSION IS GRAI	NTED	H-41		1100	
REPAIR TO TAP	Suathiny	SEWER ON THE		East	;
CUTOFF /	,	AVE. ST. TYPE OF STREET	•		
THE PREMISES BEING LOT NO		le 10 le	_, HOUSE NO.	440	<u>'</u>
WORK TO BE DONE IN ACCORDA DEPARTMENT OF PUBLIC SERVIC		E NO. 19.1971 DULY PAS	SED BY THE C	CITY COUNCIL, AND RUI	LES OF THE
NAME OF CONTRACTOR		Contractors	1. 3 3. 3		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.