


N^o 11495

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/2/02 IF SO, HOW AND LOCATION FROM 79'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 430
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Tissot
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED [Signature] 1/4/1 Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11495

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/6/02, 20

RECEIVED OF _____ FEE OF \$

FOR WHICH PERMISSION IS GRANTED Tissot Excavating

REPAIR TO TAP top sanitary SEWER ON THE East CUTOFF

OF Abble AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15179, HOUSE NO. 11430

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tissot

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.