## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6/3/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 84'	
HOUSE NO1460	- INANAULE DOWN STREAM	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAINyes	NAME OF CONTRACTOR Grabil	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	G 84'  G 84'  G 88'	<b>↑</b>
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

## Nº 11496

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			/
F	MASSILLON	I, OHIO,	5//20_
RECEIVED OF	24 dobeel Con	do	FEE OF \$
FOR WHICH PERMISSION IS GRANTED _	Offichie	v 0	
REPAIR TO TAP	SEWER ON THE		MALTA
OF	AVE. ) PE OF STREET		deadast
THE PREMISES BEING LOT NO.	Proc 857	_, HOUSÉ NO	1/460
		*	
WORK TO BE DONE IN ACCORDANCE WIT DEPARTMENT OF PUBLIC SERVICE.	'H ORDINANCE NO. 19.1971 DULY PA	SSED BY THE CIT	Y COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	Mediel	-	_

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.