N^{0} 11503

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | · |
|---|----------------------------|
| HOUSE NO. | FIRST MANHOLE DOWN STREAM |
| SIZE OF PIPE USED | CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL | OF BUILDING SERVED. |
| | |
| | No Record of Inspe |
| | |
| SIGNEDInspector for City | FILED AT ENGINEER'S OFFICE |
| | |
| REMARKS | |

Nº 11503

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| MASSILLON, OHIO, 5/70_ RECEIVED OF JALLACULULUS (STALA) FEE OF \$ |
|--|
| REPAIR TO TAP CUTOFFF OF OF OF OF OF OF OF OF O |
| THE PREMISES BEING LOT NO. PTO CEST, HOUSE NO. 1465 |
| VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| Note: This permit covers work outside of building only. Any work inside |

walls of building is subject to Massillon Board of Health regulations.