

N^o 11506

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/3/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

129'

HOUSE NO. 1520

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11506

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/7, 2020
RECEIVED OF Springhill Co. Inc. FEE OF \$ 12.50

FOR WHICH PERMISSION IS GRANTED Grubbs

REPAIR TO TAP Grubbs SEWER ON THE North SIDE
CUTOFF Grubbs

OF Grubbs AVE. ST. TYPE OF STREET Grubbs

THE PREMISES BEING LOT NO. P. O. 857, HOUSE NO. 1520

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Grubbs

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.