

Nº 11515

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/1/02

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

301'

HOUSE NO. 1517

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

*[Signature]*

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11515

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/7  
RECEIVED OF Spenshill Condo FEE OF \$ 32  
FOR WHICH PERMISSION IS GRANTED Gasbill  
REPAIR TO TAP Sanitary SEWER ON THE South SI  
CUTOFF Tyler Mill Rd AVE. ST. TYPE OF STREET asphalt  
OF Pt 01857 THE PREMISES BEING LOT NO. 1517, HOUSE NO. 1517

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Gasbill

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**