

N^o 11526

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 11526

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

RECEIVED OF Kenny Glick (MASSILLON, OHIO, 5/28 2007) FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

2 Samba SEWER ON THE East S
OF 24th St AVE. ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15583, HOUSE NO. 200

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Glick

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.