

Nº 11529

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/14/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

1120' from upstream MHI

HOUSE NO. 759

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

North arrow



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

tomorrow
6/4
No 11529

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 3, 20

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Jerry's Excavating

REPAIR TO TAP tap sanitary SEWER ON THE North SIDE
CUTOFF

OF 28th Street NW AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15536, HOUSE NO. 759

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Jerry's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.