

N^o 11530

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/2/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

90'

HOUSE NO. 2740

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes


NAME OF CONTRACTOR

Bontrager

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11530

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 06/03/02, 20

RECEIVED OF Efficient Homes FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Bortrager Excavating

REPAIR TO TAP tap sanitary SEWER ON THE North S
CUTOFF

OF Relda Circle 5th AVE. asphalt
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 15617, HOUSE NO. 2740

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bortrager

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.