

Nº 11535

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/3/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

155'

HOUSE NO. 1880

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Romon

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11535

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/1/81
RECEIVED OF Roman Plumbing FEE OF \$ 1.52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sanitary SEWER ON THE East SIDE
CUTOFF Case Western Reserve AVE. Roswell
OF _____ ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. 15993, HOUSE NO. 1580

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Roman

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.