Nº 11537

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED6/21/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	Tapped into MH
HOUSE NO622	FIRST WANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Weaver Exc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.	622 Weshington Si Na 1-10- 7-dp 36- 8-dp Topped into MH
SIGNED/ Bill Pape	FILED AT ENGINEER'S	OFFICE
REMARKS		

Nº 11537

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERN	ЛТ	TO	TAP	SEV	VER
		$\mathbf{I} \mathbf{V}$		LULU T	ILLI

1	MASSILLON, OHIO,	-
RECEIVED OF A SALLEY C	V Caratide FEE OF \$	57
FOR WHICH PERMISSION IS GRANTED	to Properties	y 5
REPAIR /	SR ON THE CLUT	5
CUTOFF	OF STREET SANGELLAND	
THE PREMISES BEING LOT NO.	1, HOUSE NO	
, , ,		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1 DEPARTMENT OF PUBLIC SERVICE.	1971 DULY PASSED BY THE CITY COUNCIL, AND HULES OF THI	<u>-</u>
NAME OF CONTRACTOR UMBANIA	<u>/</u>	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.