## Nº 11541

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM
HOUSE NO255	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	ON ID LINE AND DET TH
WAS ATTACHED TO MAIN	NAME OF CONTRACTORT. Evans Bros Exc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.  255 Warmington Rd SW
Nat to scale	22° - 13' 8" 200' 47'
SIGNED My Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 11541

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, C	OHIO,	06/25/	<u> </u>
RECEIVED OF			FEE OF \$	_/(
FOR WHICH PERMISSION IS GRANTED	Evans	Bios	Franching .	A.
REPAIR TO TAP Santaly SEV	VER ON THE		South	5
DE WASMINGTON RA CURT. TY			asprate	i
THE PREMISES BEING LOT NO			•	
·				
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 1	9.1971 DULY PASS	ED BY THE C	TY COUNCIL, AND RULES OF	= THE
DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR T. EVANS	Bros_	+ f = 3		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.