


N^o 11544

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/9/02 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 184'
HOUSE NO. 756
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Holderbaum
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11544

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/8, 2057

RECEIVED OF Halderbaum

FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE West

S

OF Avon Pl

AVE.

ST. TYPE OF STREET Residential

THE PREMISES BEING LOT NO. 4299

, HOUSE NO. 756

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Halderbaum

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**