FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 10/18/02 | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | 162' |
|---|---|--|
| HOUSE NO1304 | THE WANTEL DOWN STREAM | |
| SIZE OF PIPE USED6" | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | |
| WAS LATERAL AT CURB? Yes | | |
| WAS ATTACHED TO MAIN Yes | NAME OF CONTRACTOR | Grabil |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU | JILDING SERVED. | Tyler Mils Lone NE |
| ot la scale | | curb 1324 22° 1328 22° 1328 22° 18° 2° 2° 2° 2° 2° 2° 2° 2° 2° 2° 2° 2° 2° |
| SIGNED | FILED AT ENGINEE | ER'S OFFICE |
| REMARKS | | |

Nº 11547

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| MASSILLON, OHIO, |
|--|
| RECEIVED OF STUNDEN FEE OF \$ 5 |
| OR WHICH PERMISSION IS GRANTED |
| THE PREMISES BEING LOT NO. P+ 0 (857, HOUSE NO. 1304 |
| VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| IAME OF CONTRACTOR |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.