

Nº 11552

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED 10/18/02

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

174'

HOUSE NO. 1348

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

*[Signature]*

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N<sup>o</sup> 11552

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 7/10 20  
RECEIVED OF Springwell Condo Corp FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR  
TO TAP Sanitary SEWER ON THE north S  
CUTOFF Tyler M AVE  
OF 1st TYPE OF STREET asphalt  
THE PREMISES BEING LOT NO. P1 02857, HOUSE NO. 134/8

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Shubert

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**