

Nº 11556

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9/12/02 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 36' upstream MH

HOUSE NO. 1368

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



Firestone Exc. extended Lateral. Grabill to connect to house.
8/14/02



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11556

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/10
RECEIVED OF Springfield Land Corp FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP Sanitary SEWER ON THE North S
CUTOFF Taylor Mill Rd AVE. ST. TYPE OF STREET asphalt
OF Pt 00-857 THE PREMISES BEING LOT NO. 1368, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Gresham

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.