Nº 11557

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/12/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 36' upstream MH
HOUSE NO. 1384	THE WAS DELLOW TO THE WAY
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Grabill 1368 1348
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.
Not to scale	Firestone Exc. extended Lateral. Grabilit to connect to house. 22. 45 39. 1364 22. 1364 45. 1645. 6/14/02
SIGNED JAM INSPECTOR City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11557

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

/ MASSILLON, OHIO,
RECEIVED OF Adulahiel Could Color FEE OF \$ 3
FOR WHICH PERMISSION IS GRANTED
REPAIR TO TAP SEWER ON THE MAITH
OF JULY MILL AND ST. TYPE OF STREET LINE ALLET
THE PREMISES BEING LOT NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR WILLIAM AND A STATE OF CONTRACTOR
1

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.