## Nº 11561

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/12/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	91'	•
HOUSE NO. 1428	FIRST MANNOLE DOWN STREAM		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			,
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Grabill	1428 1438
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	JILDING SERVED.		· _]
Not la scale		N	7yer Mills Lone NE 45'41 22' 5 E 45'
<u>.</u>	e	91"	
SIGNED M Inspector for City	FILED AT ENGINEER	l'S OFFICE	
DEMARKS			

## Nº 11561

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

a/a	
// MASSILLON, OHIO,	_
RECEIVED OF JULY ASKED FEE OF \$ 50	7
FOR WHICH PERMISSION IS GRANTED	_
REPAIR TO TAP SEWER ON THE MUCH	
CUTOFF	
OF LOW WILL ST. TYPE OF STREET	
THE PREMISES BEING LOT NO. 457, HOUSE NO. 1438	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE	
DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.