Nº 11567

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED7/26/	<u>'02</u> IF \$0,	HOW AND LOCATION FROM MANHOLE DOWN STREAM	222'	
HOUSE NO1458	3	:		•
SIZE OF PIPE USED6"	DOWN	NCE FROM FIRST MANHOLE I STREAM TO DITCH AT LINE AND DEPTH		
WAS LATERAL AT CURB?	<u>s</u>			
WAS ATTACHED TO MAIN	S NAME	OF CONTRACTOR	Grabill (7
SHOW BY DIAGRAM RELATION OF	FLATERAL TO WALL OF BUILDING	SERVED.	eurb_	92° 45°
SIGNED John h	inspector for City	FILED AT ENGINEER'S	OFFICE	1454

Nº 11567

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

f	MASSILLON	I, OHIO,	1/1/20_
RECEIVED OF John Market	Liel Con	lo Comp	_ FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP CUTOFE	SEWER ON THE	<u>Air</u>	Mach.
of Con Willet Ola	AVE. / . STATYPE OF STREET.	Table	Artt
THE PREMISES BEING LOT NO.	06 857	_, HOUSE NO	1458
, ,			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCI	E NO. 19.1971 DULY PA!	SSED BY THE CITY COUN	ICIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	ail_		
//			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.