Nº 11568

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/26/02 HOUSE NO. 1464 SIZE OF PIPE USED 6" WAS LATERAL AT CURB? yes	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	122'
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Grabill Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	uilding served.	Tyler Milis Long NE
SIGNED My inspector for City	FILED AT ENGINEER'S OF	FICE
REMARKS		

Nº 11568

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

/
$//$ MASSILLON, OHIO, $///\sqrt{20}$
RECEIVED OF STANDARD COMP FEE OF \$
FOR WHICH PERMISSION IS GRANTED
REPAIR TO TAP CUTOFF CUTOFF AVE. ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 1404 STJ HOUSE NO.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR
Note: This permit covers work outside of building only. Any work inside

walls of building is subject to Massillon Board of Health regulations.