Nº 11572

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/18/02 HOUSE NO. 1484	IF SO, HOW AND LOCATION FROM 136'
10000 110.	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 6"	DOWN STREAM TO DITCH AT
WAS LATERAL AT CURB?	CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED. 136' 105' 3'dp 45.
Not to scale	4-0-c/o 15-1 Tyler Mils Lone NE
SIGNED W Inspedior for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11572

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,
RECEIVED OF SALAR CONTRACTOR OF \$
FOR WHICH PERMISSION IS GRANTED
REPAIR TO TAP SEWER ON THE MALCA
OF
THE PREMISES BEING LOT NO. P+0:857, HOUSE NO. 1454
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR
Note: This permit covers work outside of building only. Any work inside

walls of building is subject to Massillon Board of Health regulations.