## Nº 11577

REMARKS \_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 7/18/02  | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 287'             |  |
|---|---|--|
| HOUSE NO1528  |   |  |
| SIZE OF PIPE USED6"   | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |  |
| WAS LATERAL AT CURB?  |   |  |
| WAS ATTACHED TO MAIN  | NAME OF CONTRACTOR Grabill  |  |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. |   |  |
| Not to scole  | 287' 8' 45' 22' 4' - 5/0 4'! Tyer MBIs Lone NE                          |  |
| SIGNED Inspector for City                                       | FILED AT ENGINEER'S OFFICE  |  |

## $N^{0}$ 11577

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| /  | MASSILLON, OHIO,                 | 1) //(20)                    |
|--|----------------------------------|------------------------------|
| RECEIVED OF                                    | sill Cauda C                     | FEE OF \$                    |
| FOR WHICH PERMISSION IS GRANTED                |                                  |                              |
| CUTOFF A                                       | SEWER ON THE                     | M. dath                      |
| THE PREMISES BEING LOT NO. 7                   | TYRE OF STREET, HOUSE NO         | a part of                    |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N | O. 19.1971 DULY PASSED BY THE CI | TY COUNCIL, AND RULES OF THE |
| DEPARTMENT OF PUBLIC SERVICE.                  |                                  | ·                            |
| NAME OF CONTRACTOR                             | ul                               | yl<br>Hawa wa kara           |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.