

Nº 11578

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/18/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 287'

HOUSE NO. 1534

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grobill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Jeffrey M. Hg

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11578

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/1/20
RECEIVED OF Springfield Land Co. FEE OF \$ 52
FOR WHICH PERMISSION IS GRANTED _____
TO TAP REPAIR Sanitary SEWER ON THE MAIN SIDE
CUTOFF 9 OF St. Louis Ave. ST. TYPE OF STREET Asphalt
THE PREMISES BEING LOT NO. Pt 02857, HOUSE NO. 1534

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Grubbs

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**