Nº 11581

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 170'	
HOUSE NO1820		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?yes		
WAS ATTACHED TO MAIN	NAME OF CONTRACTORScholmo	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	1820 Greentree PL 1820 1820 Greentree PL 22: 45: 45: 45: 45: 45: 45: 45: 45: 45: 45	
	O 170°	
SIGNED John My FILED AT ENGINEER'S OFFICE		
Inspector for City	PILED AT ENGINEER 3 OFFICE	
REMARKS		

Nº 11581

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF JUNE A	MASSILLON, OHIO, 7/1, 20 FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED	U
CUTOFF (//	SEWER ON THE LAST AVE. STOPPE OF STREET ASPALT 17 , HOUSE NO. 1830
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE DEPARTMENT OF PUBLIC SERVICE,	NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR MCAULA	up and and the

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.