

Nº 11583

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6/26/02

IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 36'

HOUSE NO. 2415


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Steve Miller, Inc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not in scale



SIGNED [Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS	

N^o 11583

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/15, 20

RECEIVED OF Malawite

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE South

SI

OF Wilbur Ave

ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16230

, HOUSE NO. 2415

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lanza

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.