Nº 11586

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 26 26
HOUSE NO. 2077	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?yes	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR H&W
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	UILDING SERVED. c/o 157', 188' =>
Not to scale	26' 26' 26' 26' 27' University
SIGNED M M Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 11586

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

V +	_/ \	MASSILLON, OHIO,	7/207
RECEIVED OF	N KW)	J. Carrier	FEE OF \$50
FOR WHICH PERMISSION	N IS GRANTED		
REPAIR TO TAP	Sentany SE	WER ON THE	West s
of Jaw	White Company	YEL OF STREET	axplialt
THE PREMISES BEING LO	OT NO. 0 ( \$	9 9 , HOUSE NO	2077
Gr.		,	
WORK TO BE DONE IN A	CCORDANCE WITH ORDINANCE NO.	19.1971 DULY PASSED BY THE CITY C	OUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC	C SERVICE.	Ž.A.	
NAME OF CONTRACTOR	- Sauldar	<u>a and design</u> ed	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.