

Nº 11587

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/17/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

83'

HOUSE NO. 2083

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

H&W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11587

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/26/7
RECEIVED OF Hsu FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP CUTOFF Sanitary SEWER ON THE West SIDE
OF University Avenue AVE. SE ST-TYPE OF STREET Asphalt
THE PREMISES BEING LOT NO. 01899, HOUSE NO. 2083

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Schen

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.