Nº 11591

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/3002 HOUSE NO. 345 SIZE OF PIPE USED 6"	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	100'	Marian Parameter Control		
WAS LATERAL AT CURB? Yes					
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	<u>Pachan</u>			····
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.	₩	342 Shaw Awe	5' 45' 8' 45'	100'
SIGNED BILL Pappas Inspector for City	FILED AT ENGINEER	R'S OFFICE			
BEMARKS					

Nº 111591

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	7)	MASSILLON, OHIO,						
RECEIVED OF	Packed		The state	- 	FEE OF \$	<u></u>		
FOR WHICH PERMISSION IS 6	GRANTED							
TO TAP	t while	_ SEWER ON THE	4	for	th			
OF XIII	1- Que Jy 8	AVE. ST. DYPE OF STREET		asi	Halt			
THE PREMISES BEING LOT NO	برس ا		_, HOUSE NO		345			
WORK TO BE DONE IN ACCOR		NO. 19.1971 DULY PAS	SSED BY THE CI	TY COUNC	IL, AND RULES O	FTHE		
DEPARTMENT OF PUBLIC SEF	AVICE.							
NAME OF CONTRACTOR	Tother	7		_ ·				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.