

N^o 11594

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/16/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

14.3'

HOUSE NO. 1915

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale

SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11594

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

8/20

RECEIVED OF _____

Malavite

FEE OF \$ _____

56

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Shubert Ave.

SEWER ON THE _____

North

SI

OF _____

Augusta Dr. Ave.

ST. TYPE OF STREET _____

Asphalt

THE PREMISES BEING LOT NO. _____

15702

HOUSE NO. _____

1915

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.