


Nº 11595

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/2/02 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 100'
HOUSE NO. 1860
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? Yes
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Malovite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11595

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

8/2, 20

RECEIVED OF _____

Malanite

FEE OF \$ _____

50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

East

SI

OF _____

are Western Ave

AVE
ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO. _____

15992

, HOUSE NO. _____

1860

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Logan Taylor

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.