

Nº 11597

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/15/02

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 134

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH ---


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Annihilation

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11597

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, \_\_\_\_\_

08/06/02, 20\_\_\_\_

RECEIVED OF \_\_\_\_\_

Annihilation Wrecking

FEE OF \$ \_\_\_\_\_

15

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR  
TO TAP \_\_\_\_\_  
CUTOFF

cut of sanitary

SEWER ON THE \_\_\_\_\_

North

SI

OF \_\_\_\_\_

Oak Ave SE

AVE.

ST. TYPE OF STREET \_\_\_\_\_

asphalt

THE PREMISES BEING LOT NO. \_\_\_\_\_

1006

, HOUSE NO. \_\_\_\_\_

134

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR \_\_\_\_\_

Annihilation

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**